



ENF Solar Assessed Supplier

Assessment Report Presented to:

Xiamen Hopergy Photovoltaic Technology Co., Ltd.

厦门华谱光电科技有限公司

Service Commissioned by:



Service Provided by:



September 4, 2023

Report Number: <<C159ENF20230801>>

Report Date: 23/Aug./2023 Expiry Date: 22/Aug./2025

Online Verification: https://verified.chn.tuv.com





Introduction

This report has been commissioned by ENF Solar – the world's most visited solar website. Inspections have been undertaken by TÜV Rheinland – a testing service provider who have been testing solar components since 1985. TÜV Rheinland is part of TÜV Rheinland Group, a technical services company established in 1872 and employing 17,000 staff around the world.

To make these reports, TÜV Rheinland sends inspectors directly to the factories to collect data, take pictures and check documents.

TÜV Rheinland's Disclaimer:

This report reflects our findings for the particular company in concern on the date of our service only. This report does not discharge or release the factory/sellers/suppliers from their commercial, legal or contractual obligations with buyers in respect of products provided by the factory/sellers/suppliers. Any reader other that the party for which this report has been specifically issued is hereby informed that the General Conditions of Service of TÜV Rheinland contain liability limitation provisions.

The objective of validating supplier information is to provide additional confidence to buyers so that they know the information has been verified by an independent third party.

The TÜV Rheinland "Supplier Capability Assessment" program is not designed to be a performance standard but rather an information validation program against an established criterion providing potential buyers with information on the establishments stated claims and capabilities.


ENF's Disclaimer:


The information provided in this report is free of charge and for informational purposes only and does not create a business or professional services relationship between you and ENF. No judgment or warranty is made with respect to the products and services offered by the company profiled here and ENF takes no responsibility for such products or services. Any use you make of the information provided in this report is at your own risk.

This report and its contents are provided "as is" and ENF makes no representation or warranty of any kind with respect to this report. ENF expressly disclaims all express and implied warranties including, but not limited to, the implied warranties of merchantability, fitness for a particular purpose, title, and non-infringement. In no event will ENF be liable to any party for any direct, indirect, incidental, special, exemplary, consequential, or other damages (including, but not limited to, lost profits, business interruption, loss of programs or data) without regard to the form of action and whether in contract, tort, negligence, strict liability, or otherwise, arising out of or in connection with this report, any content on or accessed through this report or any site service linked to, or any copying, displaying, or use thereof.



Company Overview	4
Legal Entity	5
Human Resources	5
Export Business Capacity	6
Product Capabilities	9
R & D Capacity	13
Management Systems & Quality Control Management	15
Corporate Social Responsibility	18
Development / Expansion Plans	19
Certification & Photos	20





Company Overview

Identification	Details			
Company Name	Xiamen Hopergy F	hoto	voltaic Technology Co.,	Ltd.
	No. 630, Tonghong Road, Tong'an District, Xiamen City, Fujian Province, China			nen City, Fujian
	Contact Person :	Ms.	Siyu Chen	
Facility address	Tel:	008	6-15880248186	
	Fax:	Nil		
E-mail: siyu@hopergy.com				
URL/Web Address	https://hopergy.com			
Report Date	23/Aug./2023			
Expiry Date (24 months validity)	23/Aug./2023 22/Aug./2025			
Name of Assessor	Eric Huang			
Overall Turnover of Last Year	Confidential			
Total Building Size	6,966.73 Square Meters			
Number of Buildings	1			
Office Size	750 Square Meters	3		
Working Day	Monday to Friday		Working Hours	8:00 17:00






Legal Entity

Legal Entity				
Business License Number	91350206568418696X			
Year Established	17/Mar./2011 16/Mar./2041			
Registered Address	1F West side of Office Building, No. 630, Tonghong Road, Tong'an District, Xiamen City, Fujian Province, China			
Company Address	No. 630, Tonghong Road, Tong'an District, Xiamen City, Fujian Province, China			
Registered Capital	RMB 5,128,000			
Corporate Representative	Mr. Yang Hu			
Industry	Renewable Energy			
Products /Service	Mounting System			
Business Type	☐ Manufacturer ☐ Trading Company ☐ Combined			
Type of Ownership	□ Private Owner	☐ Pu	ublic Company	☐ Joint Venture
Type of Ownership	Stated Owned	☐ Sc	ole Proprietorship	Other

Human Resources





Department Name	Full Time Employee(s)	Part-Time Employee(s)	Total
GM Office	4	0	4
Admin. Dept.	20	0	20
Production Dept.	164	0	164
Technology Dept.	12	0	12
Quality Dept.	8	0	8
Financial Dept.	4	0	4
Sales Dept.	25	0	25
Purchasing Dept.	3	0	3
R&D Dept.	10	0	10
Warehousing Dept.	14	0	14
Totals	264	0	264

Export Business Capacity

Current Export Situation

There are 16 foreign trading employees in the company.

Working Experience	Headcount
Over 30 Years	0
21-30 Years	0
11-20 Years	0
6-10 Years	6
2-5 Years	8
Less than 2 years	2

Accepted Language	Listening & Speaking	Reading & Writing
English	Yes	Yes
Japanese	Yes	Yes
N/A	N/A	N/A



ASSESSMENT REPORT PRESENTED TO <<Xiamen Hopergy Photovoltaic Technology Co., Ltd.>>

Trade Agents Employed Overseas	⊠ Yes □ No		□ No	
Nearest Port	Xiamen Port			
Accepted Payment Terms	☐ FOB ☐ CIF ☐ EXW ☐ CFR		⊠ CFR	
Accorded Downsont Tunes	⊠ L/C		⊠ Credit Card	☐ Cash
Accepted Payment Types		☐ Money Gram	⊠ Paypal	☐ Money booker
Average lead time from product order confirmation to production delivery (products exiting the company)	15 Days			

Market Distribution (Previous 12 Months)

Market	Main Product(s)	Total Revenue (%)
North America	Mounting System	20
South America	Mounting System	8
Eastern Europe	Mounting System	11
Southeast Asia	Mounting System	5
Africa	Mounting System	5
Oceania	Mounting System	15
Middle East	Mounting System	15
Eastern Asia	Mounting System	10
Western Europe	Mounting System	11
Central America	N/A	0
Northern Europe	N/A	0
Southern Europe	N/A	0
South Asia	N/A	0

ASSESSMENT REPORT PRESENTED TO <<Xiamen Hopergy Photovoltaic Technology Co., Ltd.>>

Domestic Market	N/A	0



Product Capabilities

Production Capacity		
Product Name	Production Line Capacity (Monthly)	Actual Units Produced (Previous Year)
Mounting System	12,000 Tons/Month	Confidential

Production Machinery				
Key Machine Name	Brand & Model No.	Quantity	Condition	
Laser Cutting Machine	Benteng & FIBER PLUS6025	1	Acceptable	
Bending Machine	Deratech & TAM170	1	Acceptable	
Aluminum Cutting Machine	Dengshi & DS-1-C500	3	Acceptable	
Punching Machine	EDPS & APA45, APA60, APA110, APA160, APA200, APA400	40	Acceptable	
Shot Blasting Machine	Minruicheng & JCK100	4	Acceptable	
Automatic Welder	Panasonic & 7.5KW	6	Acceptable	
Tube Shrinking Machine	Longhua & SG76, SG114, SG140	7	Acceptable	
Automatic Tube Welder	Jinqiao & (76-114)-2500	24	Acceptable	
Purlin Machine	BMS & C60-250	8	Acceptable	





Laser Cutting Machine

Bending Machine

Aluminum Cutting Machine







Punching Machine

Shot Blasting Machine

Automatic Welder







Tube Shrinking Machine

Automatic Tube Welder

Purlin Machine







Kow'	Testino	Mac	hinory

Machine Name	Brand & Model No.	Quantity	Condition
Ultraviolet Aging Chamber	Kehui & ZN-C-II	1	Acceptable
Ozone Aging Chamber	Kehui & QL100	1	Acceptable
Hardmeter	Liboshi & HR-150A	1	Acceptable
Tensile Strength Tester	Haida & HD-B615A-S	1	Acceptable



ASSESSMENT REPORT PRESENTED TO <<Xiamen Hopergy Photovoltaic Technology Co., Ltd.>>

Fast Image Measuring Instrument	Yinghaoda & OMQ432P	1	Acceptable
Direct Reading Spectrometer	BRUKER & Q2-ION	1	Acceptable

Ultraviolet Aging Chamber

Ozone Aging Chamber

Hardmeter







Tensile Strength Tester

Fast Image Measuring Instrument

Direct Reading Spectrometer









Production Flow

Raw Materials



Punching







Drilling

Assembling

Packing







R & D Capacity

Current Situation

There are 10 R&D engineers in the company.

Education Level	Headcount
Doctorate	0
Post-Graduate	0
Graduate	2
Junior College	8
Technical School	0
High School	0

Work Experience	Headcount
Over 30 Years	0
21-30 Years	0
11-20 Years	1
6-10 Years	1
2-5 Years	8
Less than 2 years	0

Brand Situation				
Registration/application No.	Brand Name	For Approval to Use Goods	Validity Date	Ref.
47885042	Refer to the photo	Class 6	14/Sep./2021 13/Sep./2031	Refer to the photo
37030154	Refer to the photo	Class 6	07/Feb./2022 06/Feb./2032	Refer to the photo

Patent Situation							
Patent No.	The Name of the Patent	The Patent Type	Available Date	Ref.			
ZL 2019 1 0720275.5	Roof photovoltaic panel support device	The Invention Patent	11/Feb./2022	Refer to the photo			
ZL 2019 1 0708677.3	Roof photovoltaic panel bracket	The Invention Patent	13/Jul./2021	Refer to the photo			
ZL 2019 1 0454668.6	Solar cell panel fastening device	The Invention Patent	11/Sep./2020	Refer to the photo			
Does the company provide	OEM/ODM service for o	⊠ Yes	□ No				
Are there relevant design input/output, review, and verification documents available for the assessed company?			⊠ Yes	□ No			
Based on inspection, are R&D employees equipped with adequate specialized equipment?			⊠ Yes	□ No			
Do R&D employees use any specific software for designing new products?			⊠ Yes	□ No			





Development Devices

Ultraviolet Aging Chamber




Ozone Aging Chamber



Hardmeter



Tensile Strength Tester



Fast Image Measuring Instrument





Management Systems & Quality Control Management

Quality Manageme	ent System Certifica	tion		
Certification	Certified By	Certificate No.	Business Scope	Expiry Date
ISO 9001:2015	Beijing Zhongrunxing Certification Co., Ltd.	07622Q1233R2M	Design, production and sales of solar photovoltaic power generation system (metal stents and accessories)	10/Jun./2022 22/Jun./2025

Product Certification							
Certification	Certified By	Certificate No.	Product Name & Model No.	Expiry Date			
Certificate of Compliance	TUV SUD	Z2 097384 0008 Rev.00	PV Mounting System	16/Nov./2022 15/Nov./2027			
Certificate of Compliance	NJN	1888-CPR-049-CN	Steel Structure	02/Oct./2022 02/Oct./2025			
Certificate of Compliance	NJN	1888-CPR-050-CN	Aluminium Structure	02/Oct./2022 02/Oct./2025			

Test Report			
Test Report	Certified By	Product Name & Model No.	Expiry Date
Test Report	SGS	Steel Plate	22/Aug./2023

Quality Control Management							
Content	Observations / Comm	ents					
Does the company set up any inspection standards for raw materials?	⊠ Yes	□ No					
Has the company set up necessary quality inspection standards in the process of production?	⊠ Yes	□ No					
Does the company have any measures to control the management of unqualified materials after sampling, to avoid mixing up or wasting?	⊠ Yes	□ No					

Are work instructions available at the location where the processes take place?		☐ Pa		arts of the		No
ne	⊠ Yes					No
als as o are ?	⊠ Yes					No
		Observ	ations	s / Comments	S	
⊠ Y€	es					□ No
Yes, with written standard procedures		written procedur lack of consister	e but			□ No
∑ Yes, Keep for _1 year available					□ No	
Yes, the purchasing document includes all the information required		purchasi documer includes incomple	ng nt ete			□ No
Yes, with clear standard and written inspection records		inspection records to no	n out	Yes, with procedures but no inspection records		☐ No, inspections are not necessary
	als as o are? Ye writte stand proce Ye for _1 availa Ye purch docur including the inform required and winspe	Yes, with written standard procedures Yes, Keep for _1 year available Yes, the purchasing document includes all the information required Yes, with clear standard and written inspection	Yes Yes	Yes Intal line Intel Intel	Yes	Per Servations / Comments Servations / Comments

TÜVRheinland®

Observations / Comments

Content

ASSESSMENT REPORT PRESENTED TO <<Xiamen Hopergy Photovoltaic Technology Co., Ltd.>>

Has the company set up any procedure for customer feedback, including complaints, clearly recorded and maintained?	standard	Yes, with a standard feedback form but no records	records but no standard	□ No
Are there any clear procedures for handling customer complaints?	Yes, with clear procedures and written records	Yes, with clear procedures but no written records	Yes, with written records but no clear procedures	□ No
Does the company have the SOP (Standard Operation Procedure) for after-sales service? Does the company provide after-sales consulting services?	⊠ Yes			□No
Does the company implement the provisions of the National Three Warrantees (warrantee for repair/replacement /return) for their products?	☐ Yes			⊠ No



Corporate Social Responsibility

Child Labour & Forced Labor					
Content	Observations / Comments				
Is it clarified that there's no child labor in the company?	⊠ Yes	□ No			
Does the company have an explicit job management program, and take corresponding measures to check the age of the employees?	⊠ Yes	□ No			
Are the staff clearly aware of the terms of labour contract, regulations of the company and the right of free employment?	⊠ Yes	□ No			
Have the staff been forced to work overtime? Will they be fined or fired if they refuse to?	Yes	⊠ No			
Health and Safety					
Content	Observations / Comments				
Has the company set up a safety responsibility system, and distributed to all levels of supervisor and provided them with corresponding training?	⊠ Yes	□ No			
Does the company conduct regular inspection of the plant and equipment, to ensure the health and safety of the workshop at least in accordance with the law?	⊠ Yes	□ No			
Does the company regularly provide necessary safety and health training, to make the staff understand that there might be occupational hazards in their work, and take appropriate protective measures when necessary? (For example, how to use personal protective equipment safely, etc.)	⊠ Yes	□ No			
Does the company hold regular fire drills, including fire drills and evacuation drills? Do the staff clearly know how to raise an alarm, how to evacuate and how to use the fire extinguisher?	⊠ Yes	No (No regular fire drill was conducted by the factory)			
Does the company have the approval report issued by the local Fire Bureau?	Yes	⊠ No			
Does the company provide sufficient first aid equipment? Are first-aid kits and trained first-aiders available in each	⊠ Yes	☐ No (No qualified first aider available in			

workshop)

workplace?

Does the company provide clean lavatories, separating men's and ladies'?	⊠ Yes	□ No
Does the company provide clean drinking water to the staff? Is there unrestricted access to the drinking water?	⊠ Yes	□ No

Development / Expansion Plans

Company Development / Expansion Plans		
Company Development Action	Timeframe	
Keep annual growth rate of 30%	Long Term	

Certification & Photos

Certification

Certificate Photo -- Business License







Certificate Photo -- Import and Export Enterprise Registration

Certificate Photo -- Custom Clearance Registration








Certificate Photo -- Trademark



Certificate Photo -- Trademark



Certificate Photo -- Patent 1



Certificate Photo -- Patent 2



Certificate Photo -- Patent 3



Certificate Photo -- ISO9001:2015



Certificate Photo -- Certificate of Compliance 1

Certificate Photo -- Certificate of Compliance 2







Certificate Photo -- Certificate of Compliance 3

Certificate Photo -- Test Report





Company Gate



Office



Workshop



Workshop



Workshop



Warehouse



Product Photo



Product Photo






Product Photo







Product Photo

Product Photo





-- The END --