

ENF Solar Assessed Supplier

Assessment Report Presented to:

Jiangyin Titanergy Co., Ltd. 江阴市泰坦光伏材料有限公司

Service Commissioned by:



Service Provided by:



January 22, 2019

Report Number: << C159ENF20190101>> Report Date: 18/Jan./2019 Expiry Date: 17/Jan./2021 Online Verification: https://verified.chn.tuv.com

Introduction

This report has been commissioned by ENF Solar – the world's most visited solar website. Inspections have been undertaken by TÜV Rheinland – a testing service provider who have been testing solar components since 1985. TÜV Rheinland is part of TÜV Rheinland Group, a technical services company established in 1872 and employing 17,000 staff around the world.

To make these reports, TÜV Rheinland sends inspectors directly to the factories to collect data, take pictures and check documents.

TÜV Rheinland's Disclaimer:

This report reflects our findings for the particular company in concern on the date of our service only. This report does not discharge or release the factory/sellers/suppliers from their commercial, legal or contractual obligations with buyers in respect of products provided by the factory/sellers/suppliers. Any reader other that the party for which this report has been specifically issued is hereby informed that the General Conditions of Service of TÜV Rheinland contain liability limitation provisions.


The objective of validating supplier information is to provide additional confidence to buyers so that they know the information has been verified by an independent third party.

The TÜV Rheinland "Supplier Capability Assessment" program is not designed to be a performance standard but rather an information validation program against an established criterion providing potential buyers with information on the establishments stated claims and capabilities.

ENF's Disclaimer:

The information provided in this report is free of charge and for informational purposes only and does not create a business or professional services relationship between you and ENF. No judgment or warranty is made with respect to the products and services offered by the company profiled here and ENF takes no responsibility for such products or services. Any use you make of the information provided in this report is at your own risk.


This report and its contents are provided "as is" and ENF makes no representation or warranty of any kind with respect to this report. ENF expressly disclaims all express and implied warranties including, but not limited to, the implied warranties of merchantability, fitness for a particular purpose, title, and non-infringement. In no event will ENF be liable to any party for any direct, indirect, incidental, special, exemplary, consequential, or other damages (including, but not limited to, lost profits, business interruption, loss of programs or data) without regard to the form of action and whether in contract, tort, negligence, strict liability, or otherwise, arising out of or in connection with this report, any content on or accessed through this report or any site service linked to, or any copying, displaying, or use thereof.





Audit Overview

Company Overview	4
Legal Entity	5
Human Resources	5
Export Business Capacity	6
Product Capabilities	8
R & D Capacity	10
Management Systems & Quality Control Management	11
Corporate Social Responsibility	14
Development / Expansion Plans	15
Certification & Photos	15



Company Overview

Identification	Details			
CompanyName	Jiangyin Titanergy Co., Ltd.			
	No.11,Wuxiang Road, Yunting Street, Jiangyin City, Wuxi City, Jiangsu Province, China			
	Contact Person :	Mr.	Bin Xu	
Facility address	Tel:	008	6-0510-86610879	
	Fax:	008	6-0510-86610877	
	E-mail:	info	@titanergy.com	
URL/Web Address	www.titanergy.com			
Report Date	18/Jan./2019			
Expiry Date (24 months validity)	18/Jan./2019 17/Jan./2021			
Name of Assessor	Jesse Wang			
Overall Turnover of Last Year	Confidential			
Total Building Size	13,849m ²			
Number of Buildings	3			
Office Size	2,000m ²			
Working Day	Mon. to Sat. Working Hours 08:00 11:00 12:00 16:30			






Legal Entity

Legal Entity					
Business License Number	9132028108770363X7				
Year Established	13/Mar./2014	13/Mar./2014 Validity Period: 13/Mar./2014 12/Mar./2034			
Registered Address	No.400,Chengyang Road Province, China	, Yunti	ng Street, Jiangyin (City, Wuxi City, Jiangsu	
Company Address	No.11,Wuxiang Road, Yunting Street, Jiangyin City, Wuxi City, Jiangsu Province, China				
Registered Capital	RMB10,000,000				
Corporate Representative	Mr. Bin Xu				
Industry	Solar Energy Products				
Products /Service	Solar Mounting System				
Business Type		□Tra	ading Company	Combined	
Type of Ownership	Private Owner Dublic Company		Joint Venture		
	Stated Owned	So	le Proprietorship	Other	

Human Resources







Department Name	Full Time Employee(s)	Part-Time Employee(s)	Total
GM	1	0	1
VGM	2	0	2
Admin. Dept.	2	0	2
Production Dept.	31	0	31
Technology Dept.	2	0	2
Quality Dept.	3	0	3
Financial Dept.	3	0	3
Sales Dept.	9	0	9
Purchasing Dept.	3	0	3
Totals	56	0	56

Export Business Capacity

Current Export Situation

There are 4 foreign trading employees in the company.

Working Experience	Headcount		Accepted Language	Listening & Speaking	Reading & Writing
Over 30 Years	0		English	Yes	Yes
21-30Years	0		N/A	N/A	N/A
11-20 Years	0		N/A	N/A	N/A
6-10 Years	0	ĺ	N/A	N/A	N/A
2-5 Years	4]	N/A	N/A	N/A
Less than 2 years	0		N/A	N/A	N/A
Does the company have a valid export license?			⊠ Yes Export License R No.: <u>02248169</u>	egistration	□ No
rade Agents Employed Overseas		🗌 Yes		🖾 No	







Nearest Port	Shanghai Port			
Accepted Payment Terms	🖾 FOB	⊠ CIF	⊠EXW	⊠CFR
	⊠ L/C	🖂 Т/Т	☐ Credit Card	Cash
Accepted Payment Types	Union	□ MoneyGram	□Paypal	Moneybooker
Average lead time from product order confirmation to production delivery (products exiting the company)	7-15 Days			

Market Distribution(Previous 12 Months)				
Market	Main Product(s)	Total Revenue (%)		
North America	N/A	0		
South America	N/A	0		
Eastern Europe	N/A	0		
Southeast Asia	Solar Mounting System	10		
Africa	N/A	0		
Oceania	N/A	0		
Middle East	N/A	0		
Eastern Asia	N/A	0		
Western Europe	N/A	0		
Central America	N/A	0		
Northern Europe	N/A	0		
Southern Europe	N/A	0		
South Asia	N/A	0		
Domestic Market	Solar Mounting System	90		





Product Capabilities

Production Capacity					
Product Name	Production Line Capacity (Monthly)	Actual Units Produced (Previous Year)			
Solar Mounting System	50 MW	600 MW			

Production Machinery			
Key Machine Name	Brand & Model No.	Quantity	Condition
Cutting Machine	No Information	6	Acceptable
Punching Machine	J23-10T/J23-16T	11	Acceptable
Open Back Press With Fixed Bed	JF21-63	6	Acceptable
Cold Formed Steel Production Line	No Information	1	Acceptable
Assembly Line	No Information	1	Acceptable

Cutting Machine	Punching Machine	Open Back Press With Fixed Bed
Cold Formed Steel Production Line	Assembly Line	N/A
		N/A

P a g e | 8 Report Number: << C159ENF20190101>>





Key Testing Machinery			
Machine Name	Brand & Model No.	Quantity	Condition
N/A	N/A	N/A	N/A

N/A	N/A	N/A
N/A	N/A	N/A

Production Flow

1: Cutting	2: Punching	3: Assembling
<image/>		
4: Packing	5: Warehousing	N/A
		N/A





R & D Capacity

Current Situation

There are 2 R&D engineers in the company.

Education Level	Headcount	Work Experience	Headcount
Doctorate	0	Over 30 Years	0
Post-Graduate	0	21-30 Years	0
Graduate	1	11-20 Years	0
Junior College	1	6-10 Years	2
Technical School	0	2-5 Years	0
High School	0	Less than 2 years	0

Brand Situation

Registration/application No.	Brand Name	For Approval to Use Goods	Validity Date	Ref.
20280159A	Refer to the Photo	Aluminous Model Board; Metal Building Materials; Metal Door Frame; Metal Frame.	14/Sep./2017 13/Sep./2027	Photo in Section 6 (TrademarkPhotos)

Patent Situation

Patent No.	The Name of the Patent	The Patent Type	Available Date	Ref.	
ZL 2016 2 0350856.6	Solar Photovoltaic Bracket	The patent for utility model	28/Sep./2016	Refer to photo (Patent Certificate)	
ZL 2016 2 0350849.6	A Rear Foot for Solar Photovoltaic Support	The patent for utility model	28/Sep./2016	Refer to photo (Patent Certificate)	
ZL 2017 2 0182169.2	Photovoltaic Bracket L-leg Set Module	The patent for utility model	13/Oct./2017	Refer to photo (Patent Certificate)	
ZL 2016 2 0337069.8	Photovoltaic Panel Clamp for Color Steel Tile Roofing	The patent for utility model	28/Sep./2016	Refer to photo (Patent Certificate)	
Does the company provide	OEM/ODM service	for others?	Yes	🖂 No	





Are there relevant design input/output, review, and verification documents available for the assessed company?	🛛 Yes	🗌 No
Based on inspection, are R&D employees equipped with adequate specialized equipment?	🗌 Yes	🖾 No
Do R&D employees use any specific software for designing new products?	🛛 Yes	□ No

Development Devices (N/A)

N/A	N/A	N/A
N/A	N/A	N/A

Management Systems & Quality Control Management

Quality Management System Certification					
Certification	Certified By	Certificate No.	Business Scope	Expiry Date	
ISO9001:2015	BZCC,IAF	10116Q17217R0S	Manufacturing, Processing and Sales of Aluminium Frame and Photovoltaic Support for Solar Cells (Except for the Mandatory Requirements of Laws and Regulations).	30/May/2018 17/May/2019	

Product Certification					
Certification	Certified By	Certificate No.	Product Name & Model No.	Expiry Date	
UL	UL	20160429- E479241	Mounting System, Mounting Devices, Clamping Devices and Ground Lugs for Use With Photovoltaic Modules and Panels & TT-ADJUSTABLE TILT LEGS,TT-KLIPLOK,TT- ROOF HOOK	29/Apr./2016	





Test Report			
Test Report	Certified By	Product Name & Model No.	Expiry Date
N/A	N/A	N/A	N/A

Quality Control Management					
Content	Obs	ervations / Comm	ents		
Does the company set up any inspection standards for raw materials?	🛛 Yes		🗌 No		
Has the company set up necessary quality inspection standards in the process of production?	⊠ Yes		🗌 No		
Does the company have any measures to control the management of unqualified materials after sampling, to avoid mixing up or wasting?	⊠ Yes		□ No		
Are work instructions available at the location where the processes take place?			□ No		
Is personal protective equipment (PPE) needed in the production line?	⊠ Yes		🗌 No		
Is the management and usage of production materials as well as the production process executed by staff who are appropriately trained and qualified or by senior staff?	🛛 Yes		🗌 No		

Supplier Management					
Content	Obser	rvations / Comments			
Does the company have a supplier assessment procedure?	⊠ Yes		🗌 No		
Does the company establish and implement a standard procedure for purchasing contract review and approval?	Yes, with written standard procedures standard standard	ure but ent	🗌 No		





Does the company keep its supplier assessment reports?	Yes, Keep for _1 years available			🗌 No
Are the company's purchasing documents sufficient to ensure product safety control and their customers' requirements?	Yes, the purchasing document includes all the information required	Yes, however the purchasing document includes incomplete information		🗌 No
Is there a procedure to conduct random product inspections after final packaging?	Yes, with clear standard and written inspection records	Yes, with inspection records but no procedures	Yes, with procedures but no inspection records	☐ No, inspections are not necessary

After Sales Service					
Content	Observations / Comments				
Has the company set up any procedure for customer feedback, including complaints, clearly recorded and maintained?	standard	Yes, with a standard feedback form but no records	records but no standard	🗌 No	
Are there any clear procedures for handling customer complaints?	Yes, with clear procedures and written records	Yes, with clear procedures but no written records	Yes, with written records but no clear procedures	□ No	
Does the company have the SOP (Standard Operation Procedure) for after-sales service? Does the company provide after-sales consulting services?	⊠ Yes			🗌 No	
Does the company implement the provisions of the National Three Warrantees (warrantee for repair/replacement /return) for their products?	⊠ Yes		🗌 No		





Corporate Social Responsibility

Child Labour& Forced Labor				
Content	Observations / Comments			
Is it clarified that there's no child labor in the company?	🛛 Yes	□ No		
Does the company have an explicit job management program, and take corresponding measures to check the age of the employees?	⊠ Yes	□ No		
Are the staff clearly aware of the terms of labour contract, regulations of the company and the right of free employment?	⊠ Yes	□ No		
Have the staff been forced to work overtime? Will they be fined or fired if they refuse to?	☐ Yes	🖾 No		

Health and Safety

Content	Observations / Comments			
Has the company set up a safety responsibility system, and distributed to all levels of supervisor and provided them with corresponding training?	⊠ Yes	□ No		
Does the company conduct regular inspection of the plant and equipment, to ensure the health and safety of the workshop at least in accordance with the law?	⊠ Yes	□ No		
Does the company regularly provide necessary safety and health training, to make the staff understand that there might be occupational hazards in their work, and take appropriate protective measures when necessary? (For example, how to use personal protective equipment safely, etc.)	⊠ Yes	□ No		
Does the company hold regular fire drills, including fire drills and evacuation drills? Do the staff clearly know how to raise an alarm, how to evacuate and how to use the fire extinguisher?	☐ Yes	No(No regular fire drill was conducted by the factory)		
Does the company have the approval report issued by the local Fire Bureau?	🗌 Yes	🖾 No		
Does the company provide sufficient first aid equipment? Are first-aid kits and trained first-aiders available in each workplace?	☐ Yes	No(No qualified first aider available in workshop)		





Does the company provide clean lavatories, separating men's and ladies'?	⊠ Yes	□ No
Does the company provide clean drinking water to the staff? Is there unrestricted access to the drinking water?	⊠ Yes	□ No

Development / Expansion Plans

Company Development / Expansion Plans		
Company Development Action	Timeframe	
The organization is going to develop the new overseas market.	12 Months	

Certification & Photos

Certification









Page | 16 Report Number: << C159ENF20190101>>



























-- The END --



